

Field/Material Report

Report #: 88158

A.A.R. Testing Laboratory, Inc. 7126 180th Ave.N.E., Park 180, Suite C101, Redmond, WA 98052
Phone 425.881.5812 Fax 425.881.5441

Client Name: Nexus, LLC **Project Number:** 16-192
Contact: Mike Schiltz **Permit #** Not available
Client Address: 227 N.E. Bellevue Way #125 **Project Name:** K6 Detention Vault
 Bellevue, WA 98004 **Address:** 14112 79th Ave. N.E.

Date: 2/16/2016

Supplier:	Standwood Ready Mix	Air Temperature:	52 F	
Material Data:	Concrete	Concrete Temperature:	61 F	ASTM C 1064
Plant Number:		Air Content:	%	ASTM C 231
Mix Number:	554206b	Slump:	5 1/4 "	ASTM C 143
Truck Number:	83	Time Sampled:	11:30:00 AM	
Ticket Number:	120995	Added Water:	10	ByWhom: Contractor
Number of Samples:	5	Air Entrainment (oz/yard):		
Yards placed:	31.5/40	Admixtures (oz/yard):		
Design Strength:	3000			

Inspection Performed: Reinforced Concrete

Location: Foundation slab of vault

Grid Lines:

Remarks: Reinforcement per 1/S-2 and 11/SD1. Concrete placed by boom pump and internally consolidated with H/F vibration.

☒ Conforming to approved plans

Inspector: Bosma, Rory

2nd Inspector:

3rd Inspector:

Samples Tested in Accordance with ASTM: C 1231 C 31 C 172 C 39

Sample ID	Test Date	Age	Size	Area	Set #	Total Load	PSI	Method	Fracture Type
1601624	2/23/2016	7	4 X 8	12.63	1/1	40800	3230	C 1231	Cone

Distribution:

☒ Client ☒ Contractor ☐ Owner
☒ Municipality ☐ Engineer ☐ Architect
☐ Distribute Other

Date Mailed:

Tested By: Chris London

Reviewed: Mike Blackwell

All tests in accordance with the requirements of ASTM C 31 for casting and curing concrete specimens in the field excluding Section 10.1.2 (required use of a maximum-minimum thermometer). All reports are considered confidential and are the property of the client and A.A.R. Testing Laboratory, Inc. Reproduction except in full, without the written consent of A.A.R. Testing Laboratory is strictly forbidden.

Field Report

Report #: 64816

A.A.R. Testing Laboratory, Inc. 7126 180th Ave.N.E., Park 180, Suite C101, Redmond, WA 98052
Phone 425.881.5812 Fax 425.881.5441

Client: Nexus, LLC

227 N.E. Bellevue Way #125

Bellevue, WA 98004

Project Number: 16-192

Permit #: BNR15-05344

Project Name: K6 Detention Vault

Contact: Mike Schiltz

Address: 14112 79th Ave. N.E.

Inspection Performed: Resteel

Date: 2/24/2016

Time:

Temperature:

Inspected rebar for detention vault walls. Rebar conforms to detail "1/S2" for correct size and spacing. Rebar for corners conform to detail. Okay to close up walls. Covers and clearances to be verified by inspector on site for concrete placement.

Distribution:

- | | |
|---|---|
| <input checked="" type="checkbox"/> Distribute Client | <input checked="" type="checkbox"/> Distribute Contractor |
| <input type="checkbox"/> Distribute Engineer | <input type="checkbox"/> Distribute Owner |
| <input checked="" type="checkbox"/> Distribute Municipality | <input type="checkbox"/> Distribute Other |
| <input type="checkbox"/> Distribute Architect | <input type="checkbox"/> Distribute Other |

Inspector: Matthews, Bill

Reviewed by: Michele Guerrini

All reports are considered confidential and are the property of the client and A.A.R. Testing Laboratory, Inc. Reproduction except in full without the written consent of A.A.R. Testing is strictly forbidden